## **HAWICK DEPOT** – Primary Route 3

A698 Hawick to Cleikimin, A6088 Carter Bar to Bonchester Bridge, B6357 Swinnie Moor, B6358 Dunion

- 1. Leave Hawick Depot and travel to Morrisons Roundabout
- 2. Salt A698 Weensland Road to A68(T) junction at Cleikimin
- 3. Travel by A68 via Jedburgh to A6088 junction North of Carter Bar
- 4. Salt A6088 from junction North of Carter Bar to B6357 junction at Braidhaugh
- 5. Travel by A6088 to Bonchester Bridge and B6357 to C27 junction at Easter Fodderlie
- 6. Salt B6357 from Easter Fodderlie to A68 junction at Lintalee
- 7. Travel by A68 to Jedburgh and go to B6358 Castlegate / Galahill junction
- 8. Salt B6358 from Galahill junction to A698 junction at Spittal-on Rule
- 9. Return by A698, Mart Street and Mansfield Road to Depot