Location	Watercourse		Completion / Expected
Location		Description of Works	Completion Date
	Trator oo ar oo	Description of Works	Removal of Debris if
Scottish Borders	All Watercourses	Debris Clearance	considered flood risk
Scottish Borders	All Reservoirs	General Reservoir Maintenance	Annually
Ettrick Valley	Tima Water	Study to inform remedial works	Jan - Apr 2020 (Into 2020-21)
		95 metre embankment - bank	
Jedburgh	Jed Water	protection works	Oct-19
		Romannobridge Flood Protection	
		Scheme - Embankment and Kerb	
		Works - Flood Mitigation Works (1 in	
Romannobridge	Lyne Water	30 year protection for 15 properties)	Jan - Apr 2020 (Into 2020-21)
Skirling	,	Vegetation Clearance	, , , , , , , , , , , , , , , , , , , ,
Earlston	Leader Water	Tree Removal	Apr-19
		Vegetation Clearance and Warning	
Newtown St Boswells	Glen Burn	Letter to Residents	Apr-19
Burnmouth		Vegetation Clearance	May-19
Peebles	Eddleston Water	Tree Removal	Jun-19
Abbey St Bathans		Tree Removal??	Jun-19
	Ettrick Water (Selkirk		
Selkirk	FPS)	FPS Repairs	Jul-19
West Linton		Tree Removal + Bridge Works	Jul-19
Coldingham	х	Tree and Debris Removal	
Coldingham	٧	Tree and Debris Removal	
Coldingham	Z	Tree and Debris Removal	
- Jangham	Jed Water (Richmond	Tree and Besile Removal	
Jedburgh	Row FPS 1987)	Vegetation Clearance	Sep-19
Town Yetholm	10W11 0 1301)	Channel Clearance	Sep-19
TOWIT TELLIOITI		Gridinisti Glediance	06p-13