Location	Watercourse	Description of Works	Completion Date
Scottish Borders	All Watercourses	Debris Clearance	Removal of Debris if considered flood risk
Scottish Borders	All Reservoirs	General Reservoir Maintenance	Annually
Galashiels	Bakehouse Burn	Trash Screen & Wall Improvements	Aug-17
Bonchester Bridge	Rule Water	Riverbank Wall Replacement	Aug-17
Earlston	Turfford Burn	Rip Rap Protection and Removal of barrels from burn	Sep-17
Burnmouth		Seawall Repair	Summer-17
Eyemouth		Wellbraes Sea Wall Repair	Summer-17
Denholm	Un-named Burn	Letterdrop with regards to debris dumping	May-17
Eyemouth	Meeks Yard	Gate and fence repair	Oct-17
Darnick	Huntly Burn	Gravel clearance, Abbotsford Road Bridge	Sep-17
Hawick	Slitrig Water	Clearance of Landslip within Slitrig Water	Summer-17
Hawick	Teviot Water	Tree / Debris Removal	Apr-17
Hawick	Slitrig Water	Tree / Debris Removal	May-17
Jedburgh	Jed Water	Tree / Debris Removal	Jun-17
Peebles	Eddleston Water	Tree / Debris Removal	Jun-17
Hawick	Slitrig Water	Tree / Debris Removal	Oct-17
Galashiels	Gala Water	Tree / Debris Removal	Oct-17
Newcastleton	Liddel Water	Tree / Debris Removal	Nov-17
Jedburgh	Jed Water	Tree / Debris Removal	Jan-18
Hawick	Slitrig Water	Tree / Debris Removal	Feb-18
Galashiels	Gala Water	Tree Removal - Riverbank	Feb-18
Hawick	River Teviot	Tree Removal - Riverbank	Mar-18
Selkirk	Ettrick Water	Tree / Debris Removal	Apr-18
Preston	Un-named Burn	Removal of Debris	Oct-17
Houndwood	Un-named Burn	Removal of Debris	Oct-17
Jedburgh	Friars Burn	Removal of Debris	Nov-17
Hawick	Haggis Ha Burn	Removal of Debris	Dec-17
Fountainhall	Pirntaton Burn	Removal of Debris	Dec-17
Coldingham		Culvert Repair	Mar-18
Burnmouth		Culvert Repair	Mar-18