

Scottish Borders Council - Section 18: Schedule of Watercourse Clearance and Repair - April 2018-2019

Location	Watercourse	Description of Works	Completion / Expected Completion Date
Scottish Borders	All Watercourses	Debris Clearance	Removal of Debris if considered flood risk
Scottish Borders	All Reservoirs	General Reservoir Maintenance	Annually
Galashiels	Gala Water	Tree Removal - Near Sykes	May-18
Selkirk	Ettrick Water	Tree Removal	May-18
Innerleithen	Leithen Water	Tree Removal	May-18
Yetholm	Bowmont Water	Tree Removal	Jun-18
Galashiels	N/A	Sandbag Store Repair	Jun-18
Hawick	Slitrig Water	Wall Repair - The Village	Jul-18
Galashiels	Gala Water	Wall Repair	Jul-18
Galashiels	Mill Lade	Silt Removal / Clearance	Jul-18
Newtown St Boswells	Glen Burn	Vegetation Clearance	Aug-18
Broughton	N/A	Renew Sandbag Store	Aug-18
Galashiels	Bakehouse Burn	Trash Screen Replacement and Improvements	Sep-18
Jedburgh	Jed Water	River Wall Repair Works	Sep-18
Hawick	River Teviot	Flood Gate Repair Works	Sep-18
Clovenfords	Surface Water Run Off	Drainage Investigation	Nov-18
Jedburgh	Jed Water	Flood Gate Repair Works	Dec-18
Denholm	Un-named Burn	Grille Improvements	Dec-18
Peebles	Edderston Burn / River Tweed	Culvert Clearance	Dec-18
Jedburgh	Jed Water	Tree Removal	Dec-18
Darnick	Huntly Burn	Debris Removal	Jan-19
Romannobridge	Lyne Water	Tree Removal	Jan-19
Selkirk	Ettrick Water	Tree Removal	Jan-19
Hawick	Slitrig Water	Wall Repair - Slitrig Bank	Feb-19
Hawick	Dean Burn	Tree Removal	Mar-19